CRACK REPAIR AND INJECTION RANGE





0800227 339 ardex.co.nz

ARDEX RA 88 MULTI-PURPOSE EPOXY REPAIR ADHESIVE

Repairs

- 1 Broken steps
- 2 Loose railings
- 3 Rotton window sills
- 4 Vertical spall
- 5 Cracked stucco
- 6 Foundation cracks
- 7 Fountain cracks
- 8 Attach pool tiles
- 9 Door sills
- 10 Balcony rails
- 11 Ornamental concrete
- 12 Non-structural dry-rot
- 13 Pool cracks
- 14 Rotton wood 15 Boundary walls
- 16 Broken curbs
- 17 Trip hazards
- 18 Attach parking bumpers

ARDEX RA 84

FAST-CURE ACRYLIC ADHESIVE

Repairs

- 19 Driveway connection starter bars
- 20 Anchoring bolts
- 21 Anchoring railings
- 22 ARDEX crack injection capping agent
- 23 Anchoring solar panels
- 24 Pool rail

ARDEX RA 54

RAPID-CURING POLYUREA JOINT SEALANT

Repairs

- 25 Heavy-duty floor cracks
- **26** Control joints
- 27 Brick-to-concrete cracks

ARDEX RA 56

LOW VISCOSITY CRACK **REPAIR ADHESIVE**

Repairs

- 28 Warehouse cracks and spalls
- 29 Traffic spalls
- 30 Fine cracks in balconies

ARDEX RA 142

HAIRLINE CRACK STRUCTURAL INJECTION **EPOXY**

Repairs

31 Structural injection - 0.05mm – 3mm wide cracks

ARDEX RA 144

STRUCTURAL CRACK **INJECTION EPOXY**

Repairs

32 Structural injection - 3mm - 6mm wide cracks

CONCRETE CRAC

RHINO CRACK LOCK

- 40 Foundation cracks
- 41 Seismic strengthening
- 42 Structural concrete walls


ARDEX RA 040

POLYURETHANE-BASED JOINT SEALANT

- 45 Sealing between internal windows
- 46 Expansion joints with <25% movement

ACCESSORIES

ARDEX Injection T-Port ARDEX RA 54/84/88 Nozzle





INJECTION EPOXY

ARDEX RA 030

36 Moving external cracks

38 Sealing between windows

39 Expansion joints with <35% movement

and door frames

EXPANSION JOINT

SEALANT

Repairs

Repairs

- 33 Structural injection - 6mm - 10mm wide cracks
- 34 Blindside repair on basement floors

Gel-like consistency ideal for medium stated cracks and billidadie injection.

Two-part epaxy system.

Gravity feed or pressure injection.

High Strength

Cures three times stronger than concrete.

Blindside repair on basement or foundation walls

