

# ARDEX R 70 P

## **Medium Duty Polyurethane Screed**

Extremely durable and resistant to abrasion

Low maintenance costs

Resistant to many chemicals and liquids

Easy to clean and maintain high standards of hygiene

Seamless and continuous surface

Apply from 2mm to 5mm thickness

Available in a range of colours

**ARDEX Australia Pty Ltd** 

20 Powers Road Seven Hills NSW 2147 1300 788 780 technicalservices@ardexaustralia.com ardexaustralia.com **ARDEX New Zealand Ltd** 

15 Alfred Street Onehunga, Auckland 1061 0800 227 339 info@ardexnz.com ardex.co.nz

# ARDEX R 70 P

### **Medium Duty Polyurethane Screed**

#### **DESCRIPTION**

ARDEX R 70 P is a specialist applied polyurethane resin floor finish combining outstanding high chemical and abrasive resistance with an aesthetic finish. Ideally suited to aggressive areas where a seamless, joint-free finish is required and high hygiene standards are essential. Factories and general heavy duty plant and traffic areas are just some of the environments that can benefit from this tough, chemical-resistant and anti-slip system.

#### **SURFACE PREPARATION**

Ensure that the substrate is slightly rough, dry, solid and free of laitance, grease, dust or other loose particles such as paint, release agents, limescale, mortar, plaster, adhesive residues, etc., which may impair adhesion. Remove all traces of varnish, waxes, fats, oils and similar contaminants prior to mechanical preparation. Prepare substrate with specialist machinery; grinding, milling or blasting machine depending on the state of the substrate. Vacuum the substrate.

Properly treat and seal all joints or gaps in the concrete substrate where differential movement is expected (for example expansion joints). New concrete slabs must be allowed to cure for at least 14 days. Substrate tensile strength must be greater than 15 MPa.

To ensure maximum bond, grooves must be cut into the perimeter of the sub-floor, typically 8mm deep by 8mm wide. These should be inset approximately 100mm from and running parallel with the walls and adjacent to doorways etc., including any finishing edges and day joints. The grooves must have clean, square edges and the product laid into the full depth of the groove forming a perimeter anchorage. Grooves should surround areas not exceeding  $20\text{m}^2$ .

Steel decking must be clean, sound and properly supported to prevent flexing. Deck plates of less than 4mm thick are not recommended. Surfaces should be shot blasted to SA2.5 and primed using ARDEX R 5 E Epoxy Resin & Primer.

#### **PRIMING**

All appropriate substrates to receive ARDEX R 70 P must first be primed with ARDEX R 5 E. One or more coats of primer may be required depending upon the condition and porosity of the concrete substrate. The final coat of ARDEX R 5 E must be seeded with a fine (1-1.5mm) aggregate to provide a mechanical key.

#### **MIXING**

Part A & Part B Resin Components of ARDEX R 70 P must first be mixed together for 1 minute, using forced action, in a suitably sized mixing vessel. The contents

of Part C, the powder component and pigment sachet should then be introduced into the mixed resin and mixed together for a further 2 minutes to create one homogeneous mix. One or more packs may be mixed at the same time in order to maintain a quick rate of installation.

#### **APPLICATION**

For flooring applications, the mixed material should be applied to the prepared and primed surface between 8 and 24 hours after priming, using a trowel to achieve the desired thickness. As soon as the product has been laid and as work progresses, the surface should be gently rolled with a spiked roller in order to provide an even surface appearance. Do not re-roll later.

The work area should be protected during the installation process and during the initial curing time to ensure that no airborne debris can contaminate the surface of the wet resin as this will lead to unwanted blemishes in the hardened, cured surface.

All movement joints in the sub-floor must be carried through the topping and properly sealed. Construction joints and cracks not subject to movement may be overlaid but should the floor move in any way, these defects will reflect through the system. Isolation joints will need to be allowed for in areas where high thermal movement is anticipated, e.g. around ovens and freezers.

#### **LIMITATIONS**

Do not use ARDEX R 70 P where ambient and/or substrate temperatures are less than 5°C or where ambient humidity exceeds 90%. Floors should have an RH (relative humidity) of 75% or less. If ARDEX R 70 P is applied to substrates with a strength lower than 15 MPa, long term performance may be impaired.

If pot life is exceeded the mixed product loses characteristics and should be disposed of.

#### **CLEAN UP**

Clean tools and equipment immediately after use using a suitable solvent. Hardened product will need to be removed mechanically. See product safety data sheet for further information.

#### **STORAGE**

ARDEX R 70 P can be stored for up to 6 months in its original unopened packaging. The product should be stored in a dry place between 5°C and 30°C. Keep away from frost, direct sunlight and sources of heat.

ARDEX R 70 P Page 2 of 3

#### **COVERAGE**

Approximately 5m<sup>2</sup> per kit when applied at a 2mm thickness.

#### **PACKAGING**

ARDEX R 90 P is available in kits of 20kg containing four parts: Resin (Part A), hardener (Part B), filler (Part C), and a pigment sachet.

#### **TECHNICAL DATA**

Characteristics	Result
Working time @ 20°C	15 minutes
Light traffic	24 hours
Full traffic	48 hours
Full chemical cure	7 days
Bond strength	>1.5 MPa
Compressive strength	48 MPa
Flexural strength	20 MPa
Tensile strength	7 MPa

#### **PRECAUTIONS**

During mixing and application the following precautions should be observed: ensure adequate ventilation and avoid contact of the material with the eyes, nasal passages, mouth and unprotected skin. Avoid contact with the hands by wearing protective gloves and by using, if necessary, a suitable barrier cream.

In case of contact with the eyes, rinse immediately with plenty of water and seek medical advice and after contact with the skin wash immediately with plenty of soap and water (do not use solvents).

Prolonged contact with the skin should be avoided, especially where the user has an allergic reaction to resin-based materials. Always wear gloves and eye/face protection as necessary. Observe personal hygiene, particularly washing the hands after work has been completed or at any interruption whilst work is in progress. Care should be taken when removing gloves to avoid contaminating the insides. In case of accidents seek medical advice.

Additional information is in the Safety Data Sheet at ardex.co.nz

#### **COLOURS**

Indication only.



#### Toll Free Technical Services: 1800 224 070 (Australia) 0800 227 339 (New Zealand)

The technical details, recommendations and other information contained in this data sheet are given in good faith and represent the best of our knowledge and experience at the time of printing. It is your responsibility to ensure that our products are used and handled correctly and in accordance with any applicable New Zealand & Australian Standards, our instructions and recommendations and only for the uses they are intended. We also reserve the right to update information without prior notice to you to reflect our ongoing research and development program. Country specific recommendations, depending on local standards, codes of practice, building regulations or industry guidelines, may effect specific installation recommendations. The supply of our products and services is also subject to certain terms, warranties and exclusions, which may have already been disclosed to you in prior dealings or are otherwise available to you on request. You should make yourself familiar with them.

#### © ARDEX New Zealand Ltd 2019.

All aforementioned products are the trademarks of ARDEX New Zealand Ltd, its licensors and affiliates. Always refer to ardex.co.nz for the latest technical data from ARDEX New Zealand Ltd.